

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 7




FIG. 6

MJM-50X

1/5

47002600-0002222222222222




FIG. 8




FIG. 9











FIG. 10


MJM-50X

2/5







FIG. 23FIG. 24



SECTION A-A



MJM-50X

FIG. 26

4/5



MJM-50X

5/5